









PT. Pacific Firtrack
Indonesia

CUSTOMER NAME	PT. Madhani Talalah Nusantara
LOCATION	WESTPIT
INSPECTION DATE *)	5-Sep-2022

EQUIP. MODEL	D6R
SERIAL NUMBER	
EQUIP. NUMBER	BD 4012
SMR *)	17715
HOURS / WEEK *)	140
INSPECTED BY	Yudha,Zaqy,Luky

This report was developed by PAFINDO
and valid for
D6R only

COMPONENT Undercarriage	Left Side													Right Side												
	Tools	Brand	STD	LMT	HM Install	Actual	Worn%	Life Time	Replacement 100%		Replacement 120%		Tools	Brand	STD	LMT	HM Install	Actual	Worn%	Life Time	Replacement 100%		Replacement 120%			
									HM	Date	HM	Date									HM	Date	HM	Date		
 LINK HEIGHT	Depth	Berco	132.0	118.5	15649	127.0	37%	2066	19044	44875.43922	19723	14-Dec-2022	Depth	Berco	132.0	118.5	15649	127.0	37%	2066	19044	10-Nov-2022	19723	14-Dec-2022		
 LINK PITCH	Tape	Berco	813.0	825.5	15649	820.0	56%	2066	18410	9-Oct-2022	18962	6-Nov-2022	Tape	Berco	813.0	825.5	15649	818.0	40%	2066	18916	4-Nov-2022	19569	6-Dec-2022		
 BUSHING EXT	Caliper	Berco	72.6	59.4	15649	68.0	35%	2066	19149	15-Nov-2022	19849	20-Dec-2022	Caliper	Berco	72.6	59.4	15649	68.0	35%	2066	19149	15-Nov-2022	19849	20-Dec-2022		
 SHOE GROUSER	Depth	Berco	75.0	38.0	15649	53	59%	2066	18328	5-Oct-2022	18864	1-Nov-2022	Depth	Berco	75.0	38.0	15649	54	57%	2066	18391	8-Oct-2022	18940	5-Nov-2022		
 FRONT IDLER	Depth	Berco	24.0	43.0	16883	25	5%	832	20510	22-Jan-2023	21235	27-Feb-2023	Depth	Berco	24.0	43.0	16883	25	5%	832	20510	22-Jan-2023	21235	27-Feb-2023		
	Depth	Berco	24.0	43.0	16883	25	5%	832	20510	22-Jan-2023	21235	27-Feb-2023	Depth	Berco	24.0	43.0	16883	25.5	8%	832	19844	20-Dec-2022	20436	19-Jan-2023		
 CARRIER ROLLER	Caliper	Berco	199.0	158.5	1	180	47%	17714	25863	17-Oct-2023	31036	2-Jul-2024	Caliper	Berco	199.0	158.5	11966	MISS	####	5749						
 Track roller	S	Depth	Berco	15.0	35.5	11966	21	29%	5749	22593	6-May-2023	24718	21-Aug-2023	Depth	Berco	15.0	35.5	11966	24	44%	5749	20643	29-Jan-2023	22378	26-Apr-2023	
	D	Depth	Berco	15.0	35.5	11966	22	34%	5749	21804	28-Mar-2023	23772	4-Jul-2023	Depth	Berco	15.0	35.5	11966	25	49%	5749	20197	7-Jan-2023	21844	30-Mar-2023	
	S	Depth	CAT	15.0	35.5	11966	23	39%	5749	21169	24-Feb-2023	23009	27-May-2023	Depth	Berco	15.0	35.5	11966	26	54%	5749	19814	18-Dec-2022	21384	7-Mar-2023	
	D	Depth	Berco	15.0	35.5	11966	21	29%	5749	22593	6-May-2023	24718	21-Aug-2023	Depth	Berco	15.0	35.5	11966	25	49%	5749	20197	7-Jan-2023	21844	30-Mar-2023	
	S	Depth	Berco	15.0	35.5	11966	22	34%	5749	21804	28-Mar-2023	23772	4-Jul-2023	Depth	Berco	15.0	35.5	11966	25	49%	5749	20197	7-Jan-2023	21844	30-Mar-2023	
	D	Depth	Berco	15.0	35.5	11966	21	29%	5749	22593	6-May-2023	24718	21-Aug-2023	Depth	Berco	15.0	35.5	11966	24	44%	5749	20643	29-Jan-2023	22378	26-Apr-2023	
	S	Depth	CAT	15.0	35.5	11966	21	29%	5749	22593	6-May-2023	24718	21-Aug-2023	Depth	Berco	15.0	35.5	11966	26	54%	5749	19814	18-Dec-2022	21384	7-Mar-2023	
		D	Depth	Berco	15.0	35.5	11966	21	29%	5749	22593	6-May-2023	24718	21-Aug-2023	Depth	Berco	15.0	35.5	11966	24	44%	5749	20643	29-Jan-2023	22378	26-Apr-2023
 SPROCKET	Tape	Berco	225.0	203.0	15380	211	64%	2335	18307	4-Oct-2022	18892	2-Nov-2022	Tape	Berco	225.0	203.0	15380	212	59%	2335	18418	10-Oct-2022	19025	9-Nov-2022		
Track Adjuster	Tape	Genuine	0.0	147.5		78	53%						Tape	Genuine	0.0	147.5		85	58%							

Comment :
* C.Roller RH Not installed

Picture Left Side :

Picture Right Side :

